

Electrical Engineering

Electrical & Electronic Measurements

Comprehensive Theory

with Solved Examples and Practice Questions



MADE EASY
Publications



MADE EASY Publications Pvt. Ltd.

Corporate Office: 44-A/4, Kalu Sarai (Near Hauz Khas Metro Station), New Delhi-110016

E-mail: infomep@madeeasy.in

Contact: 011-45124660, 8860378007

Visit us at: www.madeeasypublications.org

Electrical & Electronic Measurements

© Copyright, by MADE EASY Publications Pvt. Ltd.

All rights are reserved. No part of this publication may be reproduced, stored in or introduced into a retrieval system, or transmitted in any form or by any means (electronic, mechanical, photo-copying, recording or otherwise), without the prior written permission of the above mentioned publisher of this book.

First Edition : 2015

Second Edition : 2016

Third Edition : 2017

Fourth Edition : 2018

Fifth Edition : 2019

Sixth Edition : 2020

Seventh Edition : 2021

Eighth Edition : 2022

Contents

Electrical & Electronic Measurements

Chapter 1

Introduction	1
1.1 Measurements and its Significance	2
1.2 Types of Instruments	3
1.3 Deflection and Null Type Instruments.....	3
1.4 Errors in Measurements and their Analysis.....	7
1.5 Types of Errors	15
1.6 Standard and their Classifications.....	20
1.7 Torques in Electromechanical Indicating Instruments ...	22
1.8 Types of Damping.....	24
1.9 Errors in Meters	25
1.10 Important Prefixes and Their Symbol	28
<i>Student Assignments-1</i>	28
<i>Student Assignments-2</i>	29

Chapter 2

Measurement and Resistance	32
2.1 Resistors.....	32
2.2 Methods of Reducing Residual Inductance and Capacitance in Resistors	33
2.3 Measurement of Low Resistance.....	35
2.4 Measurement of Medium Resistance	44
2.5 Important Definitions.....	50
2.6 Measurement of High Resistance	55
<i>Student Assignments-1</i>	59
<i>Student Assignments-2</i>	60

Chapter 3

A.C. Bridges	62
3.1 Introduction to Bridge Measurement and AC Bridges....	62
3.2 Measurement of Inductance.....	69
3.3 Wagner Earthing Device.....	87
3.4 Measurement of Frequency	91
3.5 Special Bridge circuit	94
<i>Student Assignments-1</i>	96
<i>Student Assignments-2</i>	97

Chapter 4

Electromechanical Indicating Instruments	100
4.1 Introduction	100
4.2 Moving Iron (M.I.) Instruments.....	110
4.3 General Torque Equation of Moving Iron Instruments...	110
4.4 Errors in Moving Iron Instruments	112
4.5 Electrodynamicometer Type Instruments.....	121
4.6 Applications of Electrodynamicometer Type Instruments	124
<i>Student Assignments-1</i>	142
<i>Student Assignments-2</i>	142

Chapter 5

Measurement of Power and Energy	146
5.1 Introduction	146
5.2 Measurement of Power.....	146
<i>Student Assignments-1</i>	176
<i>Student Assignments-2</i>	176

Chapter 6

Cathode Ray Oscilloscope (CRO)	179
6.1 Basics of CRO (Cathode Ray Oscilloscope).....	179
6.2 Advantages of CRO.....	179
6.3 Cathode Ray Tube (CRT)	181
6.4 Deflection Sensitivity of CRO	184
6.5 Graticule	185
6.6 Relation between Bandwidth and Rise Time	186
6.7 Lissajous Pattern.....	188
6.8 Phase Angle From the Lissajous Pattern.....	192
6.9 Special CRO	193
6.10 Probes of CRO.....	194
<i>Student Assignments-1</i>	195
<i>Student Assignments-2</i>	195

Chapter 7

Transducers..... 197

7.1 Introduction	197
7.2 Active and Passive Transducers.....	198
7.3 Analog Transducers	198
7.4 Measurement of Displacement using Transducers....	199
7.5 Applications of Hall effect Transducers	204
7.6. Strain Gauges	206
7.7 Resistance Thermometer (RTD).....	218
7.8 Thermistors	220
7.9 Application of Thermistors	222
7.10 Pyrometer	225
7.11 Bimetallic Strip	226
7.12 Measurement of Pressure	228
<i>Student Assignments-1</i>	242
<i>Student Assignments-2</i>	242

Chapter 8

Instrument Transformers 245

8.1 Introduction	245
8.2 Calculation of Ratio and Phase Angle Error of a CT ...	249
8.3 Characteristics of Current Transformers.....	253

8.4 Methods to Reduce Errors in CT	254
8.5 Effect of Secondary Open Circuit	255
8.6 Construction of Current Transformer.....	255
8.7 Equivalent Circuit Diagram of a PT	257
8.8 Errors in a Potential Transformer	258
<i>Student Assignments-1</i>	259
<i>Student Assignments-2</i>	259

Chapter 9

Miscellaneous 261

9.1 Potentiometer	261
9.2 Flux Meter	271
9.3 Telemetry	275
<i>Student Assignments-1</i>	278
<i>Student Assignments-2</i>	278

Chapter 10

Digital Meters 280

10.1 Digital Voltmeter (DVM).....	280
-----------------------------------	-----




Introduction to Electrical and Electronic Measurements

Measurement and instrumentation systems have wide applications such as measurement of electrical and physical quantities like current, voltage, power, temperature, pressure, displacement etc.

The reason for measurement arises when one wants to generate data for design or when one wants to propose a theory based on a set of measurement and instrumentation for commerce.

The measurement and instrumentation systems can also be used to locate things or events. Like employees present in a building, the epicenter of an earthquake. Sometimes, measurement systems are made a part of control system. One can observe the change in the field of measurement and instrumentation due to the introduction of new standards, and sensors.



This course on instrumentation and measurement is intended to make the engineers familiar about the art of modern instrumentation and measurement systems. It is well suited for classroom courses of engineering as well as for various competitive examinations.

Equal importance has been provided to both theory as well as problems with illustrative examples after every topic. It has been tried to cover every topic so that even a beginner understands it easily to excel in the subject of measurement and instrumentation.



Introduction

1.1 Measurements and it's Significance

The measurement of a given quantity is essentially an act or the result of comparison between the quantity (whose magnitude is unknown) and a predefined standard. Measurement is the process by which one can convert physical parameters to meaningful numbers. The measuring process is one in which the property of an object or system under consideration is compared to an accepted standard unit, a standard defined for that particular property. For the result of the measurement to be meaningful, the standard used for comparison purposes must be accurately defined and should be commonly accepted. Also, the apparatus used and the method adopted must be provable. The importance of measurement is simply expressed in the following statement of the famous physicist "Lord Kelvin":

"I often say that when you can measure what you are speaking about and can express it in numbers, you know something about it; when you can't express it in numbers your knowledge is of a meager and unsatisfactory kind."

Method of Measurement

Direct Measurement

- In this method, the measured or the unknown quantity is directly compared against a standard.
- This method of measurement sometimes produces human errors and hence gives inaccurate results.

Indirect Measurement

- This method of measurement is more accurate and more sensitive.
- These are more preferred over direct measurement.

Mechanical, Electrical and Electronic Instruments

Mechanical

- This instruments are used for stable and static conditions:
- They are unable to respond rapidly to measurements of dynamic and transient conditions because of having moving parts that are bulky, heavy are rigid possessing high inertia.

Electrical

Electrical methods of indicating the output of detectors are more rapid than mechanical methods, but they are limited time response.

Electronic

These instruments require use of semiconductor devices. The response time of these instruments are extremely small as a very small inertia of electron is only involved. The sensitivity of these instruments are also very high. Faster response, lower weight, lower power consumption are some of the advantages of an electronic instrument.

1.2 Types of Instruments

Absolute Instruments

These instruments give the magnitude of the quantity under measurement in terms of physical constants of the instruments i.e. Tangent Galvanometer, Rayleigh’s current balance.

Secondary Instruments

In these type of instruments, the quantity being measured can only be measured by observing the output indicated by the instrument. These instruments are calibrated by comparing with an absolute instrument.

1.3 Deflection and Null Type Instruments

Deflection Type

The deflection of the instrument provides a basis for determining the quantity under measurement i.e. PMMC Ammeter, Electrodynamicometer and moving iron instruments. They are less accurate, less sensitive and have faster response.




Figure-1.1 : PMMC (Deflection Type Instrument)

Null Type Instruments

In null type instruments, a zero or null indication leads to determination of the magnitude of measured quantity. Null type instruments are more accurate, highly sensitive and are less suited for measurements under dynamic conditions than deflection type instruments.




Figure-1.2 : Null Type Instrument

Calibration

The calibration of all instruments is important since it affords the opportunity to check the instrument against a known standard and subsequently to find errors and accuracy. Calibration procedures involve a comparison of the particular instrument with a primary standard or, a secondary standard or, an instrument of known accuracy.


Characteristics of Instrument and Measurement Systems

Accuracy

- It is the closeness with which an instrument reading approaches the true value of the quantity being measured.
- The accuracy can be specified in terms of inaccuracy or limits of error.
- The best way to conceive the idea of accuracy is to specify it in terms of the true value of the quantity being measured.
- The accuracy of a measurement means conformity to truth.

Precision

- It is a measure of the reproducibility of the measurements i.e. given a fixed value of a variable, precision is a measure of the degree to which successive measurements differ from one another.
- The term "Precise" means clearly or sharply defined.
- Precision is used in measurements to describe the consistency or the reproducibility of results.
- Precision instruments are not guaranteed for accuracy.



- Precision depends upon number of significant figures.
- The more is significant figures the more is precision.
- Significant figures convey actual information regarding the magnitude and the measurement precision of a quantity.

Example: 302 A (Number of significant figures = 3)
 302.10 V (Number of significant figures = 5)
 0.000030 Ω (Number of significant figures = 6)

Example - 1.1

In calculating voltage drop, a current of 4.37 A is recorded in a resistance of 31.27 Ω . Calculate the voltage drop across the resistor to the appropriate number of significant figures.

Solution:

Current, $I = 4.37\text{A}$ (3 significant figures)
 Resistance, $R = 31.27\Omega$ (4 significant figures)
 Voltage drop, $V = IR = 4.37 \times 31.27 = 136.6499$ volt

Since number of significant figures used in multiplication is 3.

So answer can be written only to a maximum of three significant figures i.e. $V = 137$

NOTE: 248 volt; 248.0 volt \Rightarrow More precised than other two.
 \Rightarrow 0.000248 MV

Example - 1.2 A reading is recorded as 23.90°C. The reading has

- (a) three significant figures
- (b) five significant figures
- (c) four significant figures
- (d) none of these

Solution: (c)

Example - 1.3 Assertion (A): A precision instrument is always accurate.

Reason (R): A precision instrument is one where the degree of reproducibility of the measurements is very good.

- (a) Both A and R are true and R is the correct explanation of A
- (b) Both A and R are true but R is NOT the correct explanation of A
- (c) A is true but R is false
- (d) A is false but R is true

Solution: (d)

Precision instruments are not guaranteed for accuracy. Refer to definition of precision.

Linearity

- If the output is proportional to input then, it is called linear.
- Non-linear behaviour of an instrument doesn't essentially lead to inaccuracy.
- Most of the time it is necessary that measurement system component should have linear characteristics. For example, the resistance used in a potentiometer should vary linearly with displacement of the sliding contact in order that the displacement is directly proportional to the sliding contact voltage. Any departure from linearity result in error in the read out system.




Figure-1.3: Linearity w.r.t. actual calibration curve and idealized straight line

Reproducibility

It is the degree of closeness with which a given value may be repeatedly measured. It may be specified in terms of units for a given period of time.

Static Sensitivity

- The "static sensitivity" of an instrument is the ratio of the magnitude of the output signal or response to the magnitude of input signal or the quantity being measured. It's units are mm/ μ A; per volts etc. depending upon type of input and output.

- Sometimes the static sensitivity is expressed as the ratio of the magnitude of the measured quantity to the magnitude of the response.




Figure-1.4: Sensitivity

$$\text{Static Sensitivity} = \frac{\text{Small change in output}}{\text{Small change in input}} = \frac{\Delta V_o}{\Delta V_i}$$

- The sensitivity of an instrument should be high and therefore, instrument should not have a range greatly exceeding the value to be measured.

$$\text{Deflection Factor} = \frac{1}{(\text{Static Sensitivity})}$$

Resolution or Discrimination

- The small measurable input change that can be measured by the instrument is called resolution or discrimination.
- If the input is slowly increased from some arbitrary (non-zero) input value, it will again be found that output doesn't change at all until a certain increment is exceeded. This increment is called resolution.

Example - 1.4 A digital voltmeter has a read-out range from 0 to 9,999 counts. Determine the resolution of the instrument in volt when the full scale reading is 9.999 V.


Solution:

Resolution of instrument = 1 count in 9,999

$$\text{Resolution} = \frac{1}{9999} \text{ count} = \frac{1}{9999} \times 9.999 = 10^{-3} \text{ volt} = 1 \text{ mV}$$

Dead Time & Dead Zone

Dead Time: The time required for the measurement to begin to respond to the changes in the measurand is known as dead time. It is the time before which the instrument begins to respond after the measured quantity has been changed.



Dead Zone: Dead zone is the largest change of input quantity for which there is no output of the instrument.




Figure-1.5: Dead Zone and Dead Time

Signal to Noise Ratio (S/N)

- Noise is an unwanted signal superimposed upon the signal of interest thereby causing a deviation of the output from its expected value.
- The ratio of desired to the unwanted noise is called signal to noise ratio and is expressed as

$$\frac{S}{N} = \frac{\text{Signal Power}}{\text{Noise Power}}$$

- In any measurement system, it is desired to have a large signal-to-noise ratio. This can be achieved by increasing the signal level without increasing the noise level or decreasing the noise level with some suitable technique.

Repeatability

It is the repetition of reading of an instrument from a given set of reading.

1.4 Errors in Measurements and their Analysis

Measurements done in a laboratory or at some other place always involve errors. No measurement is free from errors. If the precision of the equipment is adequate, no matter what its accuracy is, a discrepancy will always be observed between two measured results.

True Value

The true value of quantity to be measured may be defined as the average of an infinite number of measured values when the average deviation due to various contributing factors tends to zero.

Guarantee Errors

The accuracy and precision of an instrument depends upon its design, the material used and the workmanship that goes into making the instrument. Components are guaranteed to be within a certain percentage of the rated value. Thus, the manufacturer has to specify the deviations from the “nominal value” of a particular quantity. The limits of these deviations from the specified value are defined as “**Limiting Errors**” or “**Guarantee Errors**”.

For example, the magnitude of a resistor is 200 Ω with a limiting error of ±10 Ω. The magnitude of the resistance will be between the limits

$$R = 200 \pm 10 \Omega$$

or

$$R \geq 190 \Omega$$

and

$$R \leq 210 \Omega$$

Hence, the manufacturer guarantees that the value of the resistor lies between 190 Ω and 210 Ω .

Absolute (Relative) Limiting Error

The relative (fractional) error is defined as the ratio of the error to the specified (nominal) magnitude of a quantity.

$$\text{Relative limiting error, } \varepsilon_r = \left(\frac{\text{Measured value} - \text{True value}}{\text{True value}} \right) \times 100$$

or,

$$\% \varepsilon_r = \left(\frac{\text{Actual value} - \text{Nominal value}}{\text{Nominal Value}} \right) \times 100$$

or,

$$\% \varepsilon_r = \left(\frac{A_m - A_T}{A_T} \right) \times 100 \quad \left\{ \begin{array}{l} A_m = \text{Measured value} \\ A_T = \text{True value} \end{array} \right.$$

Now,

$$\% \varepsilon_r = \frac{A_m - A_T}{A_T} \quad \text{or} \quad \frac{A_m}{A_T} = 1 + \varepsilon_r \quad \text{or} \quad \frac{A_T}{A_m} = \frac{1}{1 + \varepsilon_r}$$

$$A_T = \left(\frac{1}{1 + \varepsilon_r} \right) A_m$$

Here,

$$\frac{1}{1 + \varepsilon_r} = \text{Correction factor}$$

NOTE: Nominal value = True value and Actual value = Measured value

Example - 1.5 A resistance has nominal value of 50 Ω . When it is measured its actual value is 60 Ω . Find the % error.

Solution:

$$\% \text{ error, } \varepsilon_r = \left(\frac{A_m - A_T}{A_T} \right) \times 100 = \left(\frac{60 - 50}{50} \right) \times 100 = 20\%$$

$$\% \text{ error} = 20\%$$

Example - 1.6 The measured value of a resistor is 100 Ω and its relative error is $\pm 10\%$ then, its true value and the range is?

Solution:

$$\varepsilon_r = \pm 10\% \text{ of } 100 = \pm 10 \Omega$$

Range,

$$A_T = (100 - 10) \text{ to } (100 + 10) = 90 \Omega \text{ to } 110 \Omega$$

Example - 1.7 The dead zone in a certain pyrometer is 0.125 percent of span. The calibration is 400°C to 1000°C. What temperature change might occur before it is detected?

(a) 0.25°C

(b) -0.50°

(c) 1.25°C

(d) 0.75°C

Solution: (b)

$$\text{Span} = 1000 - 400 = 600^\circ \text{C}$$

$$\therefore \text{Dead zone} = 0.125\% \text{ of span} = \frac{0.125}{100} \times 600 = 0.75^\circ \text{C}$$

Hence, a change of 0.75°C must occur before it is detected.

Combination of Quantities with Limiting Errors

When two or more quantities, each having a limiting error, are combined, it is advantageous to be able to compute the limiting error of the combination.

1. Sum or Difference of Two or more quantities

Let,

$$x_1 = a \pm \epsilon_{r1}$$

$$x_2 = b \pm \epsilon_{r2}$$

$$x_3 = c \pm \epsilon_{r3}$$

\therefore

$$x = x_1 + x_2 + x_3$$

or,

$$x = -x_1 - x_2 - x_3$$

So,

$$x = \pm (x_1 + x_2 + x_3)$$

Relative limiting error in x is given by

$$\epsilon_x = \pm \left(\frac{a}{a+b+c} \cdot \epsilon_{r1} + \frac{b}{a+b+c} \cdot \epsilon_{r2} + \frac{c}{a+b+c} \cdot \epsilon_{r3} \right)$$

(ϵ_x = worst possible error)

Example - 1.8

Three resistances $R_1 = 10 \pm 2\%$, $R_2 = 20 \pm 5\%$, $R_3 = 50 \pm 3\%$ are connected in series. Find the % limiting error for the series combination.

Solution:

$$\epsilon_R = \pm \left(\frac{10}{10+20+50} \times 2 + \frac{20}{10+20+50} \times 5 + \frac{50}{10+20+50} \times 3 \right)$$

or,

$$\epsilon_R = \pm 3.375\%$$

$$\% \text{ Limiting error} = \pm 3.375\%$$

Given,

$$R_T = 10 + 20 + 50 = 80\Omega$$

$$R_{\text{measured}} = (80 \pm 3.375\%)\Omega$$

2. Multiplication or Division Terms

Let,

$$x = \frac{x_1 x_2}{x_3} \quad \text{or} \quad \frac{x_2 x_3}{x_1} \quad \text{or} \quad x_1 x_2 x_3 \quad \text{or} \quad \frac{x_1}{x_2 x_3}$$

Then, relative limiting error is

$$\epsilon_x = \pm (\epsilon_{r1} + \epsilon_{r2} + \epsilon_{r3})$$


NOTE



When,

$$x = \frac{x_1 x_2}{x_2 + x_3} \quad \text{or} \quad \frac{x_1}{x_2 + x_3} \quad \text{or} \quad \frac{x_1 x_2}{x_2 - x_1}$$

Then, multiplication or division form is not applicable for finding relative limiting error.



1.10 Important Prefixes and their Symbol


Factor of Multiplication	Prefix	Symbol
10^{12}	Tetra	<i>T</i>
10^9	Giga	<i>G</i>
10^6	Mega	<i>M</i>
10^3	kilo	<i>K</i>
10^2	hecto	<i>h</i>
10^{-1}	deci	<i>d</i>
10^{-2}	Centi	<i>c</i>
10^{-3}	milli	<i>m</i>
10^{-6}	micro	<i>u</i>
10^{-9}	nano	<i>n</i>
10^{-12}	pico	<i>p</i>



Student's Assignments

1

- Q.1** What is the true value of voltage across the $500\text{ k}\Omega$ resistor connected between terminals *A* and *B* as shown in given figure? What would a voltmeter with a sensitivity of $20\text{ k}\Omega/\text{V}$ read on the following ranges : 50, 15, 5 V when connected across terminals *C* and *D*?



- Q.2** The following values were obtained from the measurements of the value of a resistor: $147.2\ \Omega$, $147.4\ \Omega$, $147.9\ \Omega$, $148.1\ \Omega$, $147.1\ \Omega$, $147.5\ \Omega$, $147.6\ \Omega$, $147.4\ \Omega$, $147.6\ \Omega$, and $147.5\ \Omega$.

Calculate:

- (i) arithmetic mean
- (ii) average deviation
- (iii) standard deviation, treating the data as finite
- (iv) standard deviation, treating the data as population.

Q.3 The four arms of a Hay's a.c. bridge are arranged as follows:

AB is a coil of unknown impedance.

BC is a non-inductance $R_1 = 1000 \Omega$ with an error of ± 1 part in 10,000.

CD is a non-reactive resistor $R_3 = 833 \pm 0.25 \Omega$ in series with no-loss capacitor $C = 1.43 \pm 0.001 \mu\text{F}$.

DA is a non-reactive resistor $R_2 = 16800 \pm 1$ part in 10,000.

The supply frequency is 50 ± 0.1 Hz. The bridge is balanced. Determine L and R of the coil and the limits or error. The balance conditions are:

$$L = \left(\frac{CR_1R_3}{1 + \omega^2C^2R_3^2} \right) \text{ and}$$

$$R = \left(\frac{R_1R_2R_3C^2\omega^2}{1 + \omega^2C^2R_3^2} \right)$$



Student's Assignments

1

Answers

1. 10 V, 8 V, 5.45 V, 2.86 V
2. (i) 147.53 Ω (ii) 0.218 Ω
(iii) 0.298 Ω (iv) 0.283 Ω
3. $L = 21 \pm 0.145$ Hz and $R = 2480 \pm 29.5 \Omega$



Student's Assignments


2

Q.1 Which of the following error is likely to occur in bridge method of measurement?

1. Residual error
 2. Frequency and waveform error
 3. Leakage and eddy current error
- (a) 1 only (b) 2 only
(c) 1 and 2 only (d) 1, 2 and 3

Q.2 A utility type voltmeter with an accuracy of $\pm 3\%$ of full scale (at 25°C) is used on 300 V scale to measure 230 V. What will be the possible percentage error and what range will the actual voltage fall within if the instrument reads 200 V?
(a) 3.9%, 200 V (b) 3.9%, 191 - 209 V
(c) 7.6%, 221 - 239 V (d) 7.6%, 200 V

Q.3 In the circuit given in the figure, the limiting error in the power dissipation ' I^2R ' in the resistor R is



- (a) 1.2% (b) 5.2%
(c) 10.2% (d) 25.2%

Q.4 A zero to 300 V voltmeter has a guaranteed accuracy of 1% full scale reading. The voltage measured by the instrument is 83 V. The percentage limiting error is
(a) 0.95 (b) 1.81
(c) 3.62 (d) 4.85

Q.5 Torque developed by an electromagnet is given as

$$F = \mu^a B^b A^c$$

- where, μ = Permeability of air in the gap
 B = Flux density in the air gap
 A = Cross-sectional area of the gap

The values of a , b and c are respectively

- (a) 1, 1 and 2 (b) -1, 1 and -2
(c) 1, 2 and -1 (d) -1, 2 and 1

Q.6 A resistor of 10 k Ω with 5% tolerance is connected in series with a 5 k Ω resistor of 10% tolerance. What is the tolerance limit of the series network?

- (a) 5% (b) 6.67%
(c) 10% (d) 8.33%

Q.7 Five Students made the following readings on a very accurate voltmeter which reads 2.13 V, 3.15 V, 2.97 V, 3.10 V and 2.99 V. What is the most probable value of the voltage?

- (a) 3.066 V (b) 3.12 V
(c) 2.99 V (d) 2.97 V
- Q.8** The power in a 3-phase, 3-wire load is measured using two 100 W full scale wattmeters W_1 and W_2 . W_1 is of accuracy class $\pm 1\%$ and reads 100 W. W_2 is of accuracy class $\pm 0.5\%$ and reads -50 W. The uncertainty in the computation of total power will be
(a) $\pm 1.5\%$ (b) $\pm 0.5\%$
(c) $\pm 4\%$ (d) $\pm 3\%$
- Q.9** Two resistances $100 \pm 5 \Omega$ and $150 \pm 15 \Omega$ are connected in series. If the errors are specified as standard deviations, the resultant error will be
(a) $\pm 10 \Omega$ (b) $\pm 10.5 \Omega$
(c) $\pm 15.8 \Omega$ (d) $\pm 20 \Omega$
- Q.10** The measurement of a quantity
(a) is an act of comparison of an unknown quantity with another quantity.
(b) is an act of comparison of an unknown quantity with a known quantity whose accuracy may be known or may not be known.
(c) is an act of comparison of an unknown quantity with a predefined acceptable standard which is accurately known.
(d) none of the above
- Q.11** A null type of instrument as compared to a deflection type instrument has
(a) a high accuracy (b) a lower sensitivity
(c) a faster response (d) all of these
- Q.12** In measurement systems, which of the following are undesirable static characteristics?
(a) Sensitivity and accuracy
(b) Drift, static error and dead zone
(c) Reproducibility and non-linearity
(d) Drift, static error, dead zone and non-linearity
- Q.13** The mean deviation \bar{D} in terms of deviations from the mean value of n readings is
(a) $\frac{\sum |d|}{n}$ (b) $\frac{\sum d}{n}$
(c) $\frac{\sqrt{\sum d^2}}{n}$ (d) $\frac{\sqrt{\sum d^2}}{n}$
- Q.14** A set of reading has a wide range and therefore it has:
(a) low precision (b) high precision
(c) low accuracy (d) high accuracy
- Q.15** The following are the desirable dynamic characteristics of a measurement system :
(a) fast response, fidelity, measuring lag and dynamic error
(b) fast response and measuring lag
(c) fidelity and measuring lag
(d) fast response and fidelity
- Q.16** The material of wires used for making resistance standards is usually
(a) Nichrome (b) Copper
(c) Manganin (d) Phosphor Bronze
- Q.17** Fluid friction damping can be used in
(a) horizontally mounted instruments
(b) vertically mounted instruments
(c) both in horizontally and vertically mounted instruments
(d) none of these
- Q.18** Permanent magnets used in instruments are hard core materials because
(a) they have broad hysteresis loop
(b) their energy density is high
(c) they have a high $(BH)_{\max}$ product
(d) all of the above

Answer Key:

- | | | | |
|---------|---------|---------|---------|
| 1. (d) | 2. (b) | 3. (b) | 4. (c) |
| 5. (d) | 6. (b) | 7. (a) | 8. (d) |
| 9. (d) | 10. (c) | 11. (a) | 12. (d) |
| 13. (a) | 14. (a) | 15. (d) | 16. (c) |
| 17. (b) | 18. (d) | | |


**Student's
Assignments**
2
Explanations
1. (d)

The various errors occurring in bridge method of measurement are (which we will see in later chapters):

⇒ Frequency error

- ⇒ Waveform error
- ⇒ Eddy Current error
- ⇒ Leakage Current error
- ⇒ Residual error

2. (b)

Accuracy = ± 3% of full scale which corresponds to ± 9 V.

So, range of reading for

$$200 \text{ V} = (200 \pm 9) \text{ V} = 191 - 209 \text{ V}$$

3. (b)

$$V_{\text{rms}} = \sqrt{\frac{1}{4} \int_0^T 4 dt} = \sqrt{2} \text{ volt}$$

4. (c)

$$1\% \text{ accuracy} = \frac{300 \times 1}{100} = 3 \text{ V}$$

$$\therefore \text{Percentage limiting error} = \frac{8}{83} \times 100 = 3.62\%$$

5. (d)

Force developed by an electromagnet is:

$$F = \frac{B^2 A}{\mu} = \mu^{-1} B^2 A^1$$

6. (b)

$$\begin{aligned} R_1 &= 10^4 \pm 5\% \Omega \\ &= 10^4 + \frac{5}{100} \times 10^4 \\ &= 10^4 \pm 500 \Omega \end{aligned}$$

$$\begin{aligned} R_2 &= 5000 \pm 10\% \Omega \\ &= 5000 \pm \frac{10}{100} \times 5000 \\ &= 5000 \pm 500 \Omega \end{aligned}$$

$$\therefore R = R_1 + R_2 = 15000 \pm 1000 \Omega$$

$$\begin{aligned} \therefore \text{Tolerance limit} &= \frac{1000}{15000} \times 100 \\ &= 6.666\% \approx 6.67\% \end{aligned}$$

7. (a)

Most probable value

$$= \left(\frac{3.12 + 3.15 + 2.97 + 3.1 + 2.99}{5} \right) = 3.066 \text{ V}$$

8. (d)

$$\begin{aligned} W_1 &= (100 \pm 1) \text{ W} \\ W_2 &= (-50 \pm 0.5) \text{ W} \end{aligned}$$

$$\begin{aligned} \therefore W_1 + W_2 &= 50 \pm \frac{1.5}{50} \times 100 \\ &= 50 \pm 3\% \end{aligned}$$

Hence, uncertainty in measurement of power

$$= \pm 3\%$$

9. (d)

The total resistance will be $R_{\text{equivalent}} = R_1 + R_2$
Hence, the resultant error will be ± 20 Ω

